## MATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS, AND RELATED MATERIALS REPLACES NCPA 1-82

MANUFACTURERS NAME						EMERGENCY	TELEPHON	IE NO.
own Metro Aerospace Coatings, Inc. P.O. Box 5695						(803)	277-1870	
Greenville, SC 29606						INFORMATION	TELEPHON	NE NO.
DATE OF PREPARATION 1/87				,	(803) 277-1870			
SEC	TION I - PRO	DUCT II	ENTIF	CATION				
PRODUCT NUMBER: 24-F2-103 ( PRODUCT NAME : Gloss Gray PRODUCT CLASS : Polyurethan	Enamel, BAC-	-707				tio: 1 to 1		
SEC	TION II - HA	AZARDOUS	S INGRI	EDIENTS				
INGREDIENT	CAS #		TLV (A	mg/cu.m.	PEL (	(OSHA)		PRESSURE @ 20°C
ه در هم چه هم چه هم چه ده و در چه چه چه چه چه چه هم چه هم هم چه هم هم چه هم چه هم چه چه چه چه چه چه چه چه چه د در در د		هٔ خند بیرهٔ متن بیرهٔ ۱۳۰ همهٔ ط			<u> </u>	به ۱۳۰۰ نامه کاف دان دی می بیدن نیبه د		
EASE COMPONENT:					•			
<pre>1-Zutyl Acetate 2-Ethoxyethylacetate</pre>	108-94-1	<10 < 5 <10	NE 150 5 25 NE	5*	NE 150 100 50 NE	15	·	NA NA 10 2 3.4 3.7
URING SOLUTION:		•						
Empolymer of HDI (Hexamethylene Diisocyanate)	28182-81-2	·			NE			NA
CI Monomer Content (Maximum) Toluene Tylene -Eutyl Acetate	822-06-0 108-88-3 1330-20-7 123-86-4	<25 < 5	.02 100 100 150		200 150 150			NA 22 21 10
A = NOT APPLICABLE	NE = NOT	ESTABĻI	SHED	*	= RESP	IRABLE DUST		
		<b>√</b>		And the state of t				a sarrang ang akirk Managaka <del>Mala</del> ng ang akirk Managaka Ang
	SECTION	III - P	HYSICA		<b></b>			
EVAPORATION RATE FASTER		SITY X	X HE	AVIER	LIG	HTER THAN AL	R	 L ,

<del>- ,</del>	SECTION IV - FIRE AND EXPLOSION HAZARD DATA
_	FLAMMABILITY CLASSIFICATION: OSHA Class IB FLASH POINT 40°F. TCC LEL 1.  DOT Paint, Flammable Liquid, (UN1263)
<b>S</b> .	_XTINGUISHING MEDIA: Use NFPA Class B extinguishers.  X FOAM "ALCOHOL"
	UNUSUAL FIRE AND EXPLOSION HAZARDS: Keep containers tightly closed. Isolate from heat, sparks, electrical equipment and open flame. Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. Self contained breathing apparatus should be worn by firefighters. During emergency conditions, overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.
	ŠPECIAL FIREFIGHTING PROCEDURES: Water spray may be ineffective. If water is used, fog nozzles are preferred. Water may be used to cool closed containers to prevent pressure buildup and possible autoignition or explosion when exposed to extreme heat.
	SECTION V - HEALTH HAZARD DATA
	EFFECTS OF OVEREXPOSURE: Can cause irritation to skin, eyes, and respiratory tract. Symptoms may be watering of eyes, dryness of throat, coughing, headache, tightness in chest or burning sensation. Allergic reactions may occur in some individuals. Headache, dizziness or nausea may be experienced by some as a result of exposure to solvents.
	MEDICAL CONDITIONS PRONE TO AGGRAVATION BY EXPOSURE: Persons with asthmatic type conditions, chronic bronchitis or other chronic respiratory diseases or recurrent skin eczema or sensitization should be excluded from working with this product.
	RIMARY ROUTE(S) OF ENTRY: X DERMAL X INHALATION INGESTION
	EMERGENCY AND FIRST AID PROCEDURES: Eye Contact; Flush with water for 15 minutes.  Consult physician. Skin Contact: Wash affected area with soap and water. Remove contaminated clothing. Consult physician. Inhalation: Remove to fresh air. Consult physician. Ingestion: Drink water to dilute. Do not induce vomiting. Consult physician.
	SECTION VI - REACTIVITY DATA
	STABILITY: UNSTABLE X STABLE
	HAZARDOUS POLYMERIZATION: MAY OCCUR X WILL NOT OCCUR HAZARDOUS DECOMPOSITION PRODUCTS: By fire - CO, CO, nitrogen oxides, traces of HCN, HBI.
	CONDITIONS TO AVOID: Contact with moisture and other materials which react with isocyanates. Temperature above maximum storage temperature.  Avoid exposure to heat, sparks, or open flames.
	INCOMPATIBILITY (MATERIALS TO AVOID)  Avoid contact with water, alcohols, amines, strong bases, metal compounds or surface active materials. Avoid contact with strong oxidizing agents.

## SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Evacuate non essential personnel. Remove all sources of ignition (sparks, flames, hot surfaces). Ventilate the area. Equip clean up crew with self contained breathing apparatus. Dike spill. Cover with sawdust, vermiculite, Fuller's earth. Collect material in open containers. WASTE DISPOSAL METHOD:

Conform to federal, state, and local regulations. Empty containers must be handled carefully due to product residue and flammable solvent vapor.

## SECTION VIII - SAFE HANDLING AND USE INFORMATION

RESPIRATORY PROTECTION: In outdoor or open areas use NIOSH approved mechanical filter respirator. In restricted ventilation areas, use NIOSH approved chemical/mechanical filters to remove vapor and particulates. In confined areas use NIOSH approved air line type respirators or hoods.

VENTILATION: Must be sufficient in volume and pattern to keep contaminant concentration below TLV (NIOSH) or PEL (OSHA).

PROTECTIVE GLOVES: Required, butyl rubber recommended.

EYE PROTECTION: Required. Use goggles, face shields or safety eyewear with sideshields.

OTHER PROTECTIVE EQUIPMENT: Protective creams where skin contact is likely. HYGIENIC PRACTICES: Wash hands before eating or using bathroom. Remove and wash contaminated clothing before reuse. Wear chemical resistant boots.

## SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Do not store above 100°F. Store large quantities only in buildings designed to comply with OSHA 1910.106. Keep containers closed and upright to prevent leakage. Do not store or use near heat, sparks, or flames.

OTHER PRECAUTIONS: Avoid breathing sanding dust (respirator required). Avoid prolonged or repeated contact with vapor or spray mist during application or curing.